




SOLDADURA

Preparado por
Ing. Boris GUERRERO B.


Soldadura v/s Remaches



RIVETED SPLICE IN WIDE FLANGE MEMBER



WELDED SPLICE IN WIDE FLANGE MEMBER



Unión por Soldadura y por Coplas





FIGURE 1-2 *Pipe joints welded and threaded.*

















B-BUTT JOINT




C-CORNER JOINT



E-EDGE JOINT




L-LAP JOINT





T-TEE JOINT



FIGURE 2-1 *The five basic joint designs.*



TEE JOINT



LAP JOINT



CORNER JOINT






FIGURE 2-2 *Applications of fillet welds—single and double.*




1. SQUARE GROOVE WELD




2. SINGLE-V GROOVE WELD




3. SINGLE-BEVEL GROOVE WELD




4. SINGLE-U GROOVE WELD



5. SINGLE-J GROOVE WELD




6. FLARE V WELD



7. FLARE BEVEL WELD

FIGURE 2-3 *The seven basic groove welds.*

Posiciones de Soldaduras



Posiciones de Soldaduras






FIGURE 2-6 *Welding positions—fillet welds—plate.*

TEST POSITION
HORIZONTAL 2G




AXIS OF PIPE
VERTICAL

Test Position
HORIZONTAL FIXED
5G



PIPE SHALL NOT BE
TURNED OR ROLLED
WHILE WELDING

TEST POSITION
6G



Axis of Pipe on 45°

FIGURE 2-7 *Welding positions—pipe welds.*




FIGURE 2-10 *Shielded metal arc welding.*




FIGURE 2-11 *Submerged arc welding.*



FIGURE 2-12 *Gas tungsten arc welding.*



FIGURE 2-13 *Plasma arc welding.*



FIGURE 2-15 *Flux-cored arc welding.*




FIGURE 2-17 *Electroslag welding.*

FIGURE 4-18 *Printed type marking on electrodes.*







FIGURE 4-13 *Circuit diagram.*



SHIELDED METAL ARC WELDING

FIGURE 4-8 *Process diagram.*





FIGURE 4-63 *Process diagram—CAW.*

FIGURE 5-11 Block diagram—SAW.







FIGURE 4-63 *Process diagram—CAW.*



NOTE IN AC ARC 50% HEAT IN ELECTRODE AND 50% HEAT IN BASE METAL.

FIGURE 4-36 *The tungsten arc.*




FIGURE 5-13 *Submerged arc head on travel carriage.*




FIGURE 6-1 *Torch brazing—manually applied.*




FIGURE 6-9 *Using oxyacetylene welding process.*




FIGURE 6-10 *The temperature of the flame.*





FIGURE 6-8 *Process diagram.*




ACETYLENE FLAME



REDUCING FLAME



NEUTRAL FLAME



OXIDIZING FLAME

FIGURE 6-11 *The three types of flame.*




FIGURE 6-13 *The apparatus required for welding with OAW.*




FIGURE 6-14 *Medium pressure oxyacetylene torch.*



GOOD, EVEN
PENETRATION

A GOOD WELD



EVEN EDGES

SMOOTH, EVEN RIPPLE

COMMON WELDING MISTAKES



TOO MUCH OXYGEN



GAS PRESSURE TOO HIGH



IRREGULAR TRAVEL SPEED



TRAVEL SPEED TOO FAST



TOO MUCH HEAT



NOT ENOUGH HEAT



INNER CONE TOO CLOSE TO BASE METAL

FIGURE 6-18 *Quality of oxyacetylene welds.*




FIGURE 6-23 *Press type spot welding machine.*




FIGURE 6-27 *Projection welding.*




FIGURE 6-28 *Resistance seam welding.*




FIGURE 6-20 *Flash welding.*




FIGURE 7-2 *Process diagram for air carbon arc cutting.*




FIGURE 7-4 *Circuit block diagram AAC.*




FIGURE 7-11 *Manual oxyacetylene cutting operation.*




FIGURE 7-10 *Process diagram oxygen cutting.*






FIGURE 7-17 *Numerical controlled oxygen cutting system.*



CORRECT CUT

Cutting lines are almost vertical and not very pronounced. Edges are square. Little slag evident.

COMMON CUTTING MISTAKES



PREHEAT FLAMES TOO SMALL

Bottom half uneven and wavy.



OXYGEN PRESSURE TOO LOW

Top edge and cutting lines uneven.




PREHEAT FLAMES TOO LARGE

Top edge badly melted. Middle section is smooth. Slag evident at bottom.



OXYGEN PRESSURE TOO HIGH AND/OR NOZZLE SIZE TOO SMALL

Deep gouges into sides of cut due to lack of control.



CUTTING SPEED TOO SLOW

Upper edge melted. Cutting lines rather coarse.



TORCH TRAVEL UNSTEADY

Cutting lines erratic and uneven.



CUTTING SPEED TOO FAST

Cutting lines curve in opposite direction of travel. Cut edge irregular.



CUTTING WAS LOST

Cut stopped at gouged areas. Usually due to excess travel speed or insufficient preheating.

CHAPTER 4

THE ARC WELDING PROCESSES—USING CC POWER

Tips for Welding with the Shielded Metal Arc Process.

There is a definite relationship between the welding current, the size of the welding electrodes, and the welding position. These must be selected so that the welder has the molten weld metal puddle under complete control at all times. If the puddle becomes too large, it becomes unmanageable and molten metal may run out of the puddle, particularly in out-of-position welding.

The welder should maintain the steady frying and crackling sound that comes with correct procedures. The shape of the molten pool and the movement of the metal at the rear of the pool serve as a guide in checking weld quality. The ripples produced on the bead should be uniform and the bead should be smooth with no overlap or undercut. The following seven factors are essential for maintaining high quality welding.

1. **Correct Electrode Type:** It is important to select the proper electrode for each job. This

should be based on information presented in the earlier part of this section.

2. **Correct Electrode Size:** Electrode size choice involves consideration of the type of electrode, welding position, joint preparation, weld size, welding current, the thickness or mass of the base metal, and the skill of the welder.
3. **Correct Current:** If the current is too high, the electrode melts too fast and the molten pool is large and irregular and hard to control. If the current is too low there is not enough heat to melt the base metal and the molten pool will be too small and will pile up and be irregular. This is shown by Figure 4-24A.
4. **Correct Arc Length:** If the arc is too long, the metal melts off the electrode in large globules which wobble from side to side giving a wide, spattered, and irregular bead with poor fusion to the base metal. It may also result in porosity, especially with low hydrogen electrodes. If the arc is too short, there is not sufficient heat in the arc at the start to melt the base metal sufficiently and the electrode often sticks to the work.

FIGURE 4-24 Welding variables: travel speed and current.








FIGURE 4-24 *Welding variables travel speed and current.*






FIGURE 4-25 *Weld examples relating to malpractices.*




FIGURE 17-47 *Types of surface cracks of welds.*





FIGURE 17-48 *Weld toe cracks and underbead cracks.*






Weld Defect Class — Cracks Appearance or Cross Section or Radiograph Class No. 100		How Defected	Responsibility	Probable Cause	Corrective Action
	Longitudinal Crack	VT	X design	<u>General</u> 1. Incorrect electrode. 2. High restraint of joint. 3. Rapid cooling of weld. 4. Improper joint preparation. 5. Fillet weld longitudinal crack.	1. Use proper or matched electrode. 2. Reduce rigidity of weldment or change welding sequence. Use higher ductility welding filler metal. 3. Use preheat and/or inner pass heat to reduce cooling rate. 4. Use proper joint for welding process. 5. Change center line of weld to avoid interface between parts.
		MT	X		
		PT	X welder		
		RT	X		
		UT	X shop		
	Longitudinal Crack	VT			
		MT	X		
		PT			
		RT	X welder		
		UT	X shop		
	Crater Crack	VT	X design	<u>Crater Crack</u> 1. Unfilled crater. 2. Crater crack in submerged arc welding.	1. Filler crater with proper technique. 2. Utilize run-out-tab.
		MT	X		
		PT	X welder		
		RT	X		
		UT	X shop		
	Transverse Crack	VT	X design	<u>Transverse Crack</u> 1. Incorrect electrode. 2. Rapid cooling. 3. Welds too small for size of parts joined.	1. Use proper electrode. 2. Use larger electrode, higher welding current or preheat. 3. Use larger weld possibly larger welding electrode.
		MT	X		
		PT	X welder		
		RT	X		
		UT	X shop		

FIGURE 17-49 Collection of weld defects—cracks.

Weld Defect Class -
Cavities
Appearance or Cross Section or Radiograph
Class No. 200



A







B



C



FIGURE 17-52 Collection of weld defects—cavities.

Weld Defect Class – Cavities Appearance or Cross Section or Radiograph Class No. 200		How Defected	Respon- sibility	Probable Cause	Corrective Action
	A	VT	X	design	<u>General</u> 1. Welding over foreign material on surface such as rust, oil, moisture, paint, etc. 2. Damp electrodes. 3. Improper base metals such as free machining or high sulphur. 4. Welding current too low.
		MT			
		PT		welder	
		RT			
		UT		shop	
	B	VT	X	design	<u>Surface Porosity</u> 1. Clean weld bevels and area adjacent to weld and keep clean. 2. Use fresh dry electrodes or rebake electrodes that have been exposed to dampness. 3. Utilize correct base metal possibility to use low hydrogen type electrodes. 4. Increase welding current.
		MT			
		PT		welder	
		RT			
		UT		shop	
	C	VT	X	design	<u>Gas Shielded Welding Processes</u> 1. Incorrect shielding gas type. 2. Incomplete gas coverage due to breeze, defective gas system, clogged nozzle, etc. 3. Moisture in the shielding system. 4. Poor gas coverage. 5. Welding over tack weld made with shielded metal arc process.
		MT	X		
		PT	X	welder	
		RT	X		
		UT	X	shop	
	D	VT	X	design	<u>Submerged Arc Welding</u> 1. Damp submerged arc flux. 2. Contaminated surface of electrode wire, dirt and/or moisture. 3. Too many fines in flux.
		MT			
		PT		welder	
		RT	X		
		UT	X	shop	




Weld Defect Class — Solid Inclusions Appearance or Cross Section or Radiograph Class No. 300			How Defected	Respon- sibility	Probable Cause	Corrective Action
 <p>A</p>	VT		design		<p><u>General</u></p> <ol style="list-style-type: none"> 1. Slag inclusion-between passes. 2. Intermittent slag inclusion at edge of bead (wagon tracks). 3. Irregular surface of bevels. 4. Incorrect welding technique or wrong current or voltage. 5. Submerged arc welding —flux inclusion. 	<ol style="list-style-type: none"> 1. Remove solidified slag after each pass. 2. Remove slag at bead edge. Utilize proper technique to avoid high crowned bead contour. 3. Provide for smooth bevel surface, grind if necessary. 4. Utilize correct welding technique for electrode type and joint design. 5. Improper direction of electrode wire. Welding current too low. Electrode wire misdirected possible correction use wire straightener. Improper joint detail.
	MT					
	PT		welder			
	RT	X		X		
	UT	X	shop			
 <p>B</p>	VT		design			
	MT					
	PT		welder			
	RT	X		X		
	UT	X	shop			
 <p>C</p>	VT		design			
	MT					
	PT		welder			
	RT	X		X		
	UT	X	shop			
				X		

FIGURE 17-53 Collection of weld defects—solid inclusions.

FIGURE 17-54 *Incomplete fusion.*





FIGURE 17-55 *Root penetration and joint penetration.*







Weld Defect Class — Appearance or Cross Section or Radiograph Class No. 400		How Defected	Respon- sibility	Probable Cause	Corrective Action	
 A		VT	X	design welder shop	General 1. Welding speed too fast. 2. Electrode too large for joint detail. 3. Welding current too low. 4. Improper joint design such as excessive root face or minimum root opening.. 5. Improper joint fit-up such as root opening too small.	1. Reduce welding speed. 2. Utilize correct size electrode. 3. Increase welding current for more penetration. 4. Utilize correct joint detail.
		MT				
		PT	X			
		RT	X			
		UT	X			
 B		VT	X	design welder shop	Shielded Metal Arc Welding 1. Irregular travel speed. 2. Irregular arc length	5. Make setup correct to agree with joint design detail. 1. High speed will reduce complete fusion, lower speed will cause complete fusion. 2. Maintain proper arc length.
		MT	X			
		PT				
		RT	X			
		UT	X			
 C		VT	X	design welder shop	Gas Metal Arc Welding 1. Incomplete fusion—(cold shut)	1. Direct arc at leading edge of puddle. Current too low, voltage too low, adjust for proper procedure. Pause too short at dwell when weaving. Increase pause to allow melting of base metal.
		MT	X			
		PT				
		RT	X			
		UT				
 D		VT	X	design welder shop	Submerged Arc Welding—Semiautomatic 1. Incomplete root fusion.	1. Failure to direct welding electrode to root of weld joint.
		MT				
		PT				
		RT	X			
		UT	X			

FIGURE 17-56 Collection of weld defects—incomplete fusion.




FIGURE 17-57 *Undercut fillet and groove and overlap.*




FIGURE 17-58 *Groove welds and various defects.*











FIGURE 17-59 *Contour of fillet welds.*

FIGURE 17-60 Collection of weld defects—incorrect shape.

Weld Defect Class — Appearance or Cross Section or Radiograph Class No. 500		How Defected		Respon- sibility	Probable Cause	Corrective Action
  A	VT	X	design		Undercutting	<ol style="list-style-type: none"> 1. Use uniform weave in groove welding pause at edges. 2. Use prescribed welding current for electrode size. 3. Use correct electrode size for size weld being made. 4. Use correct electrode with position capabilities. 5. Adjust electrode angle to fill undercut area.
	MT	X			1. Faulty electrode manipulation.	
	PT	X	welder	X	2. Welding current too high.	
	RT	X	shop		3. Incorrect electrode size (usually too large).	
	UT	X			4. Incorrect electrode for welding position.	
  B	VT		design		5. Incorrect electrode angle.	
	MT	X				
	PT		welder	X		
	RT	X	shop			
	UT	X				
  C	VT	X	design		Incorrect Profile	<ol style="list-style-type: none"> 1. Root opening too wide. 2. Welding current too high. 3. a. Welding speed too slow. b. Welding voltage too high arc length too long, correct arc length. 4. a. Voltage too high. b. Travel speed too fast. c. Root opening too wide. 5. Improper welding technique. Welding current too high. Reduce welding current. Use smaller electrode. 6. Use proper electrode type.
	MT	X			1. Excessive root penetration.	
	PT	X	welder	X	2. Travel speed too slow.	
	RT	X	shop		3. Excessive crown or reinforcement.	
	UT	X			4. Incomplete root or negative root reinforcement or "suck back" (internal concavity).	
 D	VT	X	design		5. Improper fillet contour usually wide on horizontal and not sufficient on vertical leg.	
	MT	X				
	PT	X	welder	X		
	RT	X	shop		6. Incorrect electrode type.	
	UT	X				




FIGURE 17-30 *Use of standard fillet gage.*




FIGURE 17-32 *Navy type weld gage.*







FIGURE 17-35 *Using penetrant on finished weld.*



A. LIQUID PENETRANT
APPLIED



B. EXCESS PENETRANT
REMOVED



C. DEVELOPER DRAWS PENE-
TRANT FROM CRACK.

FIGURE 17-34 *Principle of dye penetrant inspection.*




FIGURE 17-36 *Penetrant indication.*




FIGURE 17-37 *Principle of magnetic particle inspection.*




FIGURE 17-38 *Using magnetic particle inspection.*



FIGURE 17-39 *Magnetic powder indication.*




FIGURE 17-40 *Principle of radiographic inspection.*




FIGURE 17-41 *Setting up to take radiograph.*




FIGURE 17-43 *Principle of ultrasonic inspection.*



FIGURE 17-44 *Making an ultrasonic inspection of a weld.*




FIGURE 17-45 *Oscilloscope display.*




FIGURE 17-46 *45° Use of ultrasonic inspection.*




FIGURE 20-24 Arrangements for underwater welding.




FIGURE 20-25 *Underwater electrode holder for welding and cutting.*













Soldaduras Especiales


Unión de Soldadura							
Espesor (E)		METAL DEPOSITADO (Kg/ml) (Acero)					
pulg.	mm.						
1/8	3.2	0.045	0.098				
1/4	6.4	0.177	0.190	0.380		0.358	
3/8	9.5	0.396		0.638		0.605	
1/2	12.5	0.708		1.168		1.066	
5/8	16	1.103		1.731		1.707	1.089
3/4	19	1.592		2.380	1.049	2.130	1.449
1	25	2.839		3.987	2.578	3.554	2.322
1 1/4	32				3.768		3.380
1 1/2	37.5				5.193		4.648
2	51				8.680		7.736
2 1/2	63,5				13.674		11.617
3	76				18.432		16.253

Eficiencia de Deposición


(metal depositado v/s peso electrodo empleado)

PROCESOS	EFICIENCIA DEPOSICION o/o
Electrodo manual	60 - 70
MIG Sólido	90
MIG Tubular c/protección	83
MIG Tubular s/protección	79
TIG	95
Arco Sumergido	98

Velocidad de Deposición



Velocidad de Deposición



Flujo de Gas

Proceso	Flujo Gas (m ³ /hr)
MIG Sólido	0.8 - 1.2
MIG Tubular	1.0 - 1.4
TIG	0.5 - 1.0

Factor de Operación

(Tiempo con arco v/s tiempo pagado)

PROCESO	FACTOR DE OPERACION
Electrodo Manual	5 - 30
Mig Sólido	10 - 60
Mig tubular	10 - 60
Tig	5 - 20
Arco Sumergido	50 - 100

Consumibles

Procesos	Eficiencia Deposición %	Pérdida de Electrodo			Consumibles/100 kg. Metal depositado		
		Pérdida por colillas %	Total %	Eficiencia Electrodo %	Electrodo (Kg)	Fundente (Kg.)	Gas (m3)
Electrodo Manual Celulósico	60	12	52	48	155	—	—
Electrodo Manual Rutílico	70 -80	12	32 - 42	68 - 58	145 - 170	—	—
Electrodo Manual Bajo Hidrógeno	72	12	40	60	160-170	—	—
Mig (Cortocircuito)	93	2	9	91	110	—	17 - 42
Mig (Spray)	95	2	7	93	108	—	7 - 11
Tubular c/protección	83	1	18	82	122	—	4 - 20
Tubular s/protección	80	1	21	79	126	—	—
Arco Sumergido	99	1	2	98	102	85-100	—